

LEE'S AUTOMOTIVE REPAIR

BAR #: ARD250924

CAL 922673697

11273 WHITE ROCK RD

RANCHO CORDOVA, CA 95742

Phone: 916-852-6414 FAX: 916-852-6431

Invoice No.

72017

Page 1

Order Date 06/27/17 02:59 pm

Paid: 12/30/99 12:00 am

Ref: FIN CALLED

ASK ABOUT OUR TIRE SPECIALS !!!!!**DOJ/BFS**

11181 SUN CENTER DR.

RANCHO CORDOVA CA 95670

HOWARD [REDACTED]

OFFICE: 916-210-5421

02 CHEV. (ATC) P-30 WHITE

Mileage in:11622 out:

Lic: [REDACTED] CA V8Cyl 5.7 Eng

Vin: [REDACTED]

Eq:

Fleet # 90012922

Job01 RADIATOR INSPECTION**Labor: 1.00 hrs @ \$108.00/hr= N/C**

RADIATOR HOSE ON THE INTAKE SIDE POPPED OFF WHILE DRIVING. CLAMP ON HOSE WAS LOOSE AND DOES NOT LOOK LIKE IT IS THE CORRECT ON FOR THE HOSE. CUSTOMER REATTACHED HOSE BEST THEY COULD AND TOPPED OFF COOLING SYSTEM WITH A DIFFERENT KIND OF FLUID. CHECK HOSE FOR CRACKS AND REPLACE CLAMP.

NOTES FOR TECH: CUSTOMER WOULD LIKE THE RADIATOR FLUID CLEANED UP AS IT MADE A MESS WHEN THE HOSE CAME OFF.

Tech Notes For Customer: Replaced spring clamp with band clamp. Tested for leaks no leaks at this time. cleaned engine bay for coolant mess.

Status: Completed Tech: IH

Job02 COOLING SYSTEM FLUSH**Labor: 1.25 hrs @ \$108.00/hr= N/C**

GLOBAL

COOLANT-N (List 23.95)

3.0 @

20.37 =\$

N/C

DRAIN & FLUSH COOLING SYSTEM WITH NEW FLUID. TEST FOR LEAKS AND OPERATION.

Tech Notes For Customer: Flushed cooling system used new coolant. Tested for leaks no leaks at this time.

Status: Completed Tech: IH

Job03 HYDRAULIC LIFT SYSTEM**Labor: 1.00 hrs @ \$108.00/hr= N/C**

HYDRAULIC LIFT SYSTEM INSTALLED BY US. THE SYSTEM IS GIVING OUT AN ERROR MESSAGE WHEN THE AUTO LEVEL IS ENGAGED. CUSTOMER IS MANUALLY PUTTING THE LEGS DOWN TO THE BLOCKS AND THEN HITTING THE AUTO LEVEL BUTTON. IS THERE ANOTHER PROCEDURE NEEDED TO FOLLOW? CHECK AND ADVISE.

----->----->----->---Continued on the next page--->----->----->----->

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) _____

9/6/17

LEE'S AUTOMOTIVE REPAIR

BAR #: ARD250924

CAL 922673697

11273 WHITE ROCK RD

RANCHO CORDOVA, CA 95742

Phone: 916-852-6414 FAX: 916-852-6431

Invoice No.**72017****Page 2**

Order Date 06/27/17 02:59 pm

Paid: 12/30/99 12:00 am

Ref: FIN CALLED

ASK ABOUT OUR TIRE SPECIALS !!!!!**Job03 HYDRAULIC LIFT SYSTEM**

Tech Notes For Customer: Performed zero point calibration per service Manuel and now there is no more error codes and auto level works properly at this time.

Status: Completed Tech: BWF**Job04 MANUAL LEG INSPECTION****Labor: 1.00 hrs @ \$108.00/hr= N/C**

LEVER & ROD ASSEMBLY USED TO PUT THE LEGS DOWN GETS STUCK AFTER SETTING. THE BOLT HOLES THAT THE ROD SLIDES THROUGH APPEAR TO HAVE MISSHAPEN FOR AN "O" TO AN OBLONG SHAPE THAT ALLOWS THE ROD TO SIT IN A SORT OF DITCH. POSSIBLE THIS WAS CAUSED BY OVERLOADING THE LEGS AND IS THE RESULT OF THE LEVER GETTING STUCK IN THIS "DITCH." CHECK AND ADVISE SYSTEM IS SUITED AND APPROPRIATE FOR DOJ USE.

Status: Completed Tech: BWF**Job05 DRIVER MIRROR INSPECTION****Labor: 1.00 hrs @ \$108.00/hr= N/C**

DRIVER MIRROR WAS REINSTALLED WITH A NEW GROMMET & BOLT. WHILE DRIVING, THE MIRROR WILL FLEX AND DOESN'T HOLD STEADY DUE TO WIND. SEE IF WE CAN MAKE A STURDIER BASE TO HOLD THE MIRROR IN PLACE WHILE LEAVING THE ADJUSTABILITY AVAILABLE.

Tech Notes For Customer: Snugged bolts on mount a little more. (Still adjustable) test drove up to 70 mph. Mirror stays in place.

Status: Completed Tech: BWF**Job06 TIRE INSPECTION****Labor: 0.10 hrs @ \$108.00/hr= N/C**

TIRES MAY BE TOO THIN FOR THE VEHICLE. CHECK AND ADVISE.

Tech Notes For Customer: Checked vin plate says tire size is 8r 19.5. Tire are 8r 19.5. Tires are manufactor recommended.

Status: Completed Tech: BWF**Job07 RADIO INSPECTION****Labor: 1.00 hrs @ \$108.00/hr= N/C**

----->----->----->---Continued on the next page--->----->----->----->

LEE'S AUTOMOTIVE REPAIR

BAR #: ARD250924

CAL 922673697

11273 WHITE ROCK RD

RANCHO CORDOVA, CA 95742

Phone: 916-852-6414 FAX: 916-852-6431

Invoice No.**72017****Page 4**

Order Date 06/27/17 02:59 pm

Paid: 12/30/99 12:00 am

Ref: FIN CALLED

ASK ABOUT OUR TIRE SPECIALS !!!!!**SIGNATURE**

Warranty on parts and labor is 1 year or 12000 mileage whichever comes first unless otherwise specified on repair order detail. Warranty work has to be performed in our shop & cannot exceed the original cost of repair. Exclusions are general wear items (i.e.: fluids and filters, brake pads and rotors), and trim pieces. Customer supplied parts do not receive any warranty, nor do used parts other than a possible warranty on the part (not labor) directly from the vendor.

Payments to LEE'S AUTOMOTIVE REPAIR**Cost Summary**

Status: Paid Work Order

Payments:

1 09/06/17 0.00 Other

Labor	0.00
Parts	0.00
Subtotal	0.00
Total	\$0.00
Payments	0.00
Bal Due	0.00

Thank you for choosing LEE'S AUTOMOTIVE REPAIR